

Sets, Kits, And Outfits, Supplementary Equipment, Forestry Company

SC: 5180-95-N41
NSN: 5180-00-285-2059
LIN: U59373

System Description

Support logging and sawmill operations to produce rough lumber and timber pilings per day and forestry operations.

This system is not currently in reset.

Reset Type

Reset Work (Field Level) - Work performed to correct equipment faults that are performed at the ORG/DS level; performed by unit level soldiers, augmented by contractor as required.

Reset Strategy

n/a

Reset Procedures

- Replace worn, broken, missing components IAW supply catalog.
- Reorder consumables IAW SC.

Reset Responsibility

Unit

Reset Location

This system is not currently in reset.

- Contact Information -

877.4.PMSKOT (877.476.7568)
rock-pm-skot@conus.army.mil